FAA Airworthiness Directives Compliance Record

Company:

Sunset Key Ventures LLC

Aircraft Registration No: N692CJ

Category: Airframe

Model: DA 40

Position:

ATP Revision: 06/18/2019

P/N:

Manufacturer: Diamond Aircraft

S/N: 40.1137

Issue Number Effective Date Amendment #	Description	F307 NO. 100	Method of Compliance	Recur	Next Due	Facility Cert No. / Type Authorized By Signed
2014-13-08 08/27/2014	To correct an incorrect compliance time and to modify the aft main spar in the cabin area to ensure the, contd.	Hrs:	N/A due to aircraft serial number 40.1137 not listed in this AD.		Hrs:	Dillon's Aviation, Inc. AP2387643451A/ Ernest D. Rawls
2011-21-10 11/16/2011	To remove the VCS compressor and mount, as a result of excessive wear, which could result in the air, contd.	 Hrs: C:	N/A due to date of installation of system listed in this AD. Date of install was post AD. Date of install 04/11/2012.		D: Hrs: C:	Dillon's Aviation, Inc. AP238764345IA/ Ernest D. Rawls
2010-25-01 , O1/11/2011	To change emergency open doors procedure and retrofit the rear passenger door retaining bracket, which if not, contd.		N/A complied with during manufacturing.	No	D: Hrs: C:	Dillon's Aviation, Inc. AP238764345IA/ Ernest D. Rawls

Category: Engine

Manufacturer: Lycoming Engines

P/N:

Model: IO-360-M1A

S/N: L-35603-51E

						Facility
Issue Number						Cert No. / Type
Effective Date			Method of			Authorized By
Amendment #	Description	Complied	Compliance	Recur	Next Due	Signed

ssue Number Effective Date Amendment #	Description	Complied	Method of Compliance	Recur	Next Due	Facility Cert No. / Type Authorized By Signed
2017-16-11 08/15/2017	To prevent connecting rod failure which	Hrs: C:	N/A due to engine serial number L-35603-51E is not listed in Table 1 of Lycoming MSB632B and parts listed and ship dates listed in Table 2 of Lycoming MSB632B do not apply.	No	D: Hrs: C:	Dillon's Aviation AP238764345IA/ Ernest D. Rawls
2015-19-07 11/03/2015	injector fuel lines, which could lead to	06/18/2019 Hrs: 766.6 C:	C/W by inspection per par (e)(1)(ii) and per Lycoming MSB342G.	Yes	D: Hrs: 876.6 C:	Dillon's Aviation, Inc. AP238764345IA/ Ernest D. Rawls
2015-02-07 03/11/2015	To prevent the propeller governor shaft set screw from coming loose, causing damage to the engine and,contd.	 Hrs: C:	N/A due to engine is not a wide deck aerobatic reciprocating engine as stated in this AD.	No	D: Hrs: C:	Dillon's Aviation, Inc. AP238764345IA/ Ernest D. Rawls
2012-19-01 10/24/2012	To prevent failure of the crankshaft, which will result in total engine power loss, inflight engine, contd.	 Hrs: C:	N/A due to engine no listed in tables 1-4 of Lycoming MSB569A or crankshaft not listed in table 5 of Lycoming MSB569A.		D: Hrs: C:	Dillon's Aviation, Inc. AP238764345IA/ Ernest D. Rawls
2012-03-06 C 02/24/2012	To prevent an in-flight engine shutdown due to a failed fuel servo diaphragm, and damage to the airplane	Hrs: C:	N/A due to fuel serve diaphragm PN listed in this AD is not installed on this aircraft.	No	D: Hrs: C:	Dillon's Aviation, Inc. AP238764345IA/ Ernest D. Rawls
2004-10-14 C 06/25/2004 39-13644	[Recurring] To prevent loosening or failure of the crankshaft gear retaining bolt, which may cause sudden engine failure	 Hrs: C:	N/A due to this engine not involved in sudden stoppage.	Yes	D: Hrs: C:	Dillon's Aviation, Inc. AP238764345IA/ Ernest D. Rawls vision: 06/18/2019

Category: Propeller

Manufacturer: Hartzell Propeller

Model: HC-C2YR-1

P/N:

S/N: NS695B

ssue Number Effective Date Amendment #	Description	Complied		Recur	Next Due	Facility Cert No. / Type Authorized By Signed
2009-22-03 11/12/2009 39-16054	[Recurring] To prevent failure of the propeller hub causing blade separation and subsequent loss of airplane control	 Hrs: C:	N/A due to propeller hub serial number is a suffix serial number and non "E" suffix. Propeller hub serial number NS695B.		D: Hrs: C:	Dillon's Aviation, Inc. AP238764345IA/ Ernest D. Rawls
Category: Magnetos		Position:	LH	82 00 00 0000000000000000000000000000	ATP Revision:	06/18/2019
Manufacturer: Slick		P/N: 66G	R25SANN			8
Model: 4347		S/N: 110	82329			
Issue Number Effective Date Amendment #	Description	Complied	Method of Compliance	Recur	Next Due	Facility Cert No. / Type Authorized By Signed
		 Hrs: C:			D: Hrs: C:	
Category: Magnetos		Position:	RH		ATP Revision:	06/18/2019
Manufacturer: Slick		P/N: 660	P-0SANN			
Model: 4370		S/N: 110	90084			
Issue Number Effective Date Amendment #	Description	Complied	Method of Compliance	Recur	Next Due	Facility Cert No. / Type Authorized By Signed
		 Hrs:			D: Hrs:	

Issue Number Effective Date Amendment #	Description		Method of Compliance	Recur		Facility Cert No. / Type Authorized By Signed
	I.	 Hrs: C:			D: Hrs: C:	

Position: **ATP Revision:** 06/18/2019 Category: Starter

P/N: 31B22105 Manufacturer: Sky-Tec

S/N: FNE-481142 Model: 149NL

Facility Issue Number Cert No. / Type **Effective Date Authorized By** Method of Amendment # Signed Next Due Description Complied Compliance Recur

Issue Number Effective Date Amendment #	Description	Complied	Method of Compliance	Recur	Next Due	Facility Cert No. / Type Authorized By Signed
-		 Hrs: C:			D: Hrs: C:	06/10/2010

Category: Fuel Injected System

Position:

ATP Revision: 06/18/2019

Manufacturer: Precision Airmotive

P/N: 61J22633

Model: RSA-10AD1

S/N: 70E71803

Issue Number Effective Date Amendment #	Description	Complied	Method of Compliance	Recur	Next Due	Facility Cert No. / Type Authorized By Signed
2012-03-06 C 02/24/2012	To prevent an in-flight engine shutdown due to a failed fuel servo diaphragm, and damage to the airplane	 Hrs: C:	N/A due to fuel servo diaphragm PN installed is not listed in this AD.	No	D: Hrs: C:	Dillon's Aviation, Inc. AP238764345IA/ Ernest D. Rawls
2009-02-03 02/09/2009	[Recurring] To prevent a lean running engine, which could result in a substantial loss of engine power and subsequent, contd.	 Hrs: C:	N/A due to fuel servo plug gasket PN installed is not listed in this AD.	Yes	D: Hrs: C:	Dillon's Aviation, Inc. AP238764345IA/ Ernest/D. Rawls

Category: Alternators

Position:

ATP Revision: 06/18/2019

Manufacturer: Hartzell Engine Tech

P/N: 32C19553

Model: ALE-8421R Alternator

S/N: H-L090835

Issue Number Effective Date Amendment #	Description	Complied	Method of Compliance	Recur		Facility Cert No. / Type Authorized By Signed
3		 Hrs: C:			D: Hrs: C:	

Category: Governors

Position:

ATP Revision: 06/18/2019

Manufacturer: Hartzell Propeller

P/N: S-1-6

Model: S-1-6

S/N: G1068NJ

Issue Number Effective Date Amendment #	Description	Complied	Method of Compliance	Recur	Next Due	Facility Cert No. / Type Authorized By Signed
					D:	
_	the state of the s	Hrs:			Hrs:	
	787	C:			C:	
			No. 25 and			
Catagorius Innition	Cyatama	Positio	n:	0.91	ATP Re	evision: 06/18/2019

Category: Ignition Systems

Manufacturer: ACS Products Company

P/N: A-510-2

Model: IGNITION SWITCHES

S/N: N/A

Issue Number Effective Date Amendment #	Description	Complied	Method of Compliance	Recur	Next Due	Facility Cert No. / Type Authorized By Signed
93-05-06 04/29/1993	[Recurring] TO PREVENT FAILURE OF IGNITION SWITCHES	02/13/2012 Hrs: 0 C:	AD was installed new at Diamond Aircraft	Yes	D: Hrs: 2000 C:	Dillon's Aviation, Inc. AP238764345IA/ Ernest D. Rawls
2 24	310, 1 A 111		Industries #161-93. Not due until AFTT: 2000.0.			Emy D. Jas

Category: Safety Belts

Position:

ATP Revision: 06/18/2019

Manufacturer: AmSafe

P/N:

Model: Safety Belts

S/N:

Issue Number Effective Date Amendment #	Description	Complied	Method of Compliance	Recur		Facility Cert No. / Type Authorized By Signed
(2 ETO	 Hrs: C:			D: Hrs: C:	, e