6
US Department
of Transportation
Federal Aviation
Administration

MAJOR REPAIR AND ALTERATION (Airframe, Powerplant, Propeller, or Appliance)

-	Form Approved OMB No. 2129-0020 2/28/2011	Electronic Tracking Number
-		or FAA Use Only

03-28-2012

INSTRUCTIONS: Print or type all entries. See Title 14 CFR §43.9, Part 43 Appendix B, and AC 43.9-1 (or subsequent revision thereof) for instructions and disposition of this form. This report is required by law (49 U.S.C. §44701). Failure to report can result in a civil penalty for each such violation. (49 U.S.C. §46301(a)) Nationality and Registration Mark Serial No. N318DS 40.1137 1. Aircraft Model Series DIAMOND AIRCRAFT IND INC DA 40 Name (As shown on registration certificate) Address (As shown on registration certificate) Address 204 RELEASE CIR 2. Owner RALEIGH State NC FIVE STAR MARKETING INC Zip 27615-1695 Country UNITED STATES 3. For FAA Use Only the data identified here in complies with the applicable airworthiness requirements and is approved only for the above described aircraft, subject to conformity inspection by a person authorized in FAP 43, section 43.7 4. Type 5. Unit Identification Repair Alteration Unit Make Model Serial No 1 AIRFRAME (As described in Item 1 above) POWERPLANT PROPELLER ype APPLIANCE Manufacturer 6. Conformity Statement A. Agency's Name and Address B. Kind of Agency PREMIER AIRCRAFT SERVICE U. S. Certificated Mechanic Manufacturer Address 5540 NW 23RD AVE Foreign Certificated Mechanic C. Certificate No. City **FT LAUDERDALE** State ELORIDA Certificated Repair Station 33309 Zin Country UNITED STATES Certificated Maintenance Organization 9PRR402B I certify that the repair and/or alteration made to the unit(s) identified in item 5 above and described on the reverse or attachments hereto have been made in accordance with the requirements of Part 43 of the U.S. Federal Aviation Regulations and that the information furnished herein is true and correct to the best of my knowledge. Extended range fuel Signature/Date of Authorized Individual per 14 CFR Part 43 App. B RIAN ARIAS 03-28-2012 7. Approval for Return to Service Pursuant to the authority given persons specified below, the unit identified in item 5 Administrator of the Federal Aviation Administration and is ✓ Approved was inspected in the manner prescribed by the Rejected FAA Fit. Standards Manufacturer Maintenance Organization Persons Approved by Canadian Inspector Department of Transport BY FAA Designee Other (Specify) Repair Station Inspection Authorization Certificate or Signature/Date of Authorized Individual Designation No.

9PRR402B

ADRIAN ARIAS

NOTICE

Weight and balance or operating limitation changes shall be entered in the appropriate aircraft record. An alteration must be compatible with all previous alterations to assure continued conformity with the applicable airworthiness requirements.

8. Description of Work Accomplished

		N318DS		3-28-2012
Installed B&C Specialties Model BC stallation Instructions 410LST3.DOC //11/2012, and DC Aerospace Drawin	(from STC #SA01066V	VI). Form 8110-3 provi	ance with Ba	Date &C Specialties Produ Aerospace dated
Utilized all wiring as supplied by B&0 ritch supplied by Diamond and annun h FAR23.1361.	C Specialty Products.	Circuit protection prov	ided by fact	ory circuit breakers. It panel and comply
The alternator required 25 in-lbs of to 00 drive pad per TCDS E1E10.	orque and has an 18 in	I-Ib overhang moment	which is wi	thin limits for an ANI
Instructions for Continued Airworthin A-BC217-aA.wpd.	ness provided by B&C (Specialties Products d	ocument IC	A-BC410 Rev. A, ar
Flight Manual Supplement FMS-N31	8DS installed into POH			
Weight and balance revised. Equipm	ment list revised.			
This additional system does not adverse ernator output allows full use of the G	ersely effect aircraft sys 31000 avionics, less that	stem performance and an 13 amps load, plus	in fact enh another 7 a	ances aircraft safety imps excess power
pacity.				
oacity.			78102	econ D I
pacity.	END			
pacity.				
eacity.			79300	
pacity.				
acity.				
acity.				
pacity.				
acity.				
pacity.				ACTION OF THE PROPERTY OF THE
pacity.		2A19A MA		
acity.		ZAIFIA MA		
acity.				
acity.				
pacity.		SAIFIA MA		

- ALL PITOT-STATIC LINES, EXPOSED CONNECTORS OR ANY LOOSE WRING BUNDLES AFFECTED DURING THE REMOVAL — INSTALLATION PHASE OF THE DATA HEREIN ARE TO BE CAPPED, PROTECTED, TIED BACK, ETC., AND IDENTIFIED AS TO ITS FUNCTION.
- ALL COMPONENTS, PANELS, EQUIPMENT, MISC. SWITCHES, ETC., THAT ARE CAUSED TO BE REMOVED BY THE DATA HEREIN, ARE TO BE BAGGED AND IDENTIFIED AND STORED IN A SUITABLE PLACE.
- CABLE/WRING CLAMPS SHALL BE USED OF SUFFICIENT SIZE AND AT LOCATED AT EVERY STRUCTURE CROSSING OR MAXIMUM SEPARATION OF 18 INCHES. ENOUGH WIRE SLACK WILL BE PROVIDED FOR AT LEAST 3 RE—CONNECTS.
- 4. ALL CABLE WRE USED SHALL MEET MIL-C-27500-16-xx, ALL SINGLE WRE USED SHALL MEET MIL-W-22759-16-xx AND HAVE WIRE NUMBERS AS SHOWN HEREIN MARKED EITHER BY LASER, INK-JET OR SLEEVES.
- NEW INSTALLATIONS OF WIRE / CABLE SHALL FOLLOW THE SAME ROUTING AS REMOVED / INSTALLED SYSTEMS WHERE POSSIBLE.
- ALL GROUNDS TO BE TREATED IN ACCORDANCE WITH THE AIRCRAFT MANUFACTURES MAINTENANCE / WRING PRACTICES MANUAL AND / OR FAA AC 43-13-1x, 2x AS APPLICABLE.
- ALL UNMARKED WIRES ARE NOT TO EXCEED 6 INCHES IN LENGTH. ALL WIRES TO BE 22 AWG UNLESS OTHERWISE NOTED.
- 8. MAXIMUM WIRE LENGTHS: UNLESS OTHERWISE NOTED:
 - A. CHASSIS GROUND 16 INCHES
 - B. SHIELD GROUND 18 INCHES
 - C. EXPOSED FROM SHIELD 3 INCHES
- SHIELD CONTINUITY SHALL BE MAINTAINED THROUGH ALL BREAK POINTS, UNLESS OTHERWISE SHOWN.
- 10. PERFORM "COLD WIRING" CHECK BEFORE APPLYING POWER.
- 11. REMOVE TOP ENGINE COWL, REMOVE BATTERY AIRCRAFT POWER
- 12. REFERENCE SHEET 2 FOR BC410 ALTERNATOR INSTALL
- REFERENCE SHEET 3 FOR ANNUNCIATOR / ALTERNATOR CONTROL SWITCH / CIRCUIT BREAKERS INSTALLATION
- 14. REFERENCE SHEET 4 FOR WIRING / ANCILLARY COMPONENT INSTALLATION
- 15. ROUTE ALL NEW WIRING AWAY FROM CHAGE POINTS AND FLIGHT CONTROLS USING NYLON WIRE TIES. CHECK THE WIRE CLEARANCES FROM FLIGHT AND ENGINE CONTROLS. CHECK FLIGHT AND ENGINE CONTROLS AT AT FULL CONTROL STOPS.
- 16. RE-CONNECT AIRCRAFT BATTERY

- 17. PERFORM FUCTIONAL TEST OF NEW BC410 ALTERNATOR INSTALLATION:
 - A. CLOSE THE "STBY ALT", "FIELD" AND "SENSE" CIRCUIT BREAKER AND THE "STBY ALT" MASTER SWITCH, BATTERY SWITCH "ON"
 - B. USING A HIGH DIGITAL VOLTAMETER, CHECK THE VOLTAGE BETWEEN PIN 7 OF THE REGULATOR AND BOTH THE AIRFRAME AND THE BATTERY NEGATIVE POST. VERIFY READING <0 VOLTS DC.
 - C. USE PIN 7 OF THE REGULATOR OR AIRFRAME AS NEGATIVE REFERENCE. VERIFY THE VOLTAGE ON PIN 1 OF THE BC203—20 (REGULATOR) IS EQUAL TO BUS VOLTAGE.
 - D. USE PIN 7 OF THE REGULATOR OR AIRFRAME. CHECK VOLTAGE ON PIN 6 OF THE REGULATOR, VERIFY VOLTAGE IS WITHIN 1.0 VOLT DC OF THE BUS VOLTAGE.
 - E. USE PIN 7 OF THE REGULATOR OR AIRFRAME. CHECK VOLTAGE ON PIN 5 OF THE REGULATOR READS 13 TO 15 VOLTS DC.
 - F. "TRIP" THE "STBY ALT" "FIELD" CIRCUIT BREAKER.
 VERIFY VOLTAGE ON PIN 6 READS "0" VOLTS, AND
 ANNUNCIATOR "STBY ALT ON" EXTINGUISHES. RESET
 CIRCUIT BREAKER.
 - G. "TRIP" THE "STBY ALT" CIRCUIT BREAKER. VERIFY VOLTAGES ON PIN 6 READS "O" VOLTS, AND AND ANNUNCIATOR "STBY ALT ON" EXTINGUISHES. RESET CIRCUIT BREAKER.
 - H. "TRIP" THE STBY ALT "SENSE" CIRCUIT BREAKER.
 VERIFY VOLTAGE ON PIN 1 OF THE REGULATOR READS
 "O" VOLTS, AND AND ANNUNCIATOR "STBY ALT ON"
 EXTINGUISHES. RESET CIRCUIT BREAKER.
 - AT THE ALTERNATOR, VERIFY VOLTAGE ON "F" FIELD TERMINAL AND ENGINE GROUND, IS SAME AS VOLTAGE MEASURED ON PIN 5 OF THE REGULATOR WITHIN +-1.0 VOLT. ALTERNATOR CONNECTOR MUST REMAIN CONNECTED FOR THIS TEST.

- J. PREPARE AIRCRAFT FOR ENIGNE RUN. REINSTALL COWLING.
- K. PERFORM A NORAML ENIGINE START AND ALLOW THE ENGINE TO REACH PROPER OPERATING TEMP.
- L. ASSURE THAT THE "STB ALT" AND "STBY ALT SENSE" CIRCUIT BREAKERS, AND "ATBY ALT" MASTER SWITCH ARE IN THE "ON" POSITION.
 - M. REDUCE SYSTEM ELECTRICAL LOADS TO APPROXIMATELY 10 TO 15 AMPS.
- N. SET ENGINE RPM TO 2000 RPM MINIMUM.
- O. SWITCH PRIMARY ALTERNATOR FIELD SWITCH "OFF".
- P. CHECK THAT THE "STBY ALT ON" ANNUNCIATOR ILLUMINATES.
- Q. INCREASE THE ELECTRICAL LOAD TO OVER 20 AMPS, VERIFY THE "STBY ALT ON" ANNUNCIATOR ILLUMINATES AND IS BLINKING. REDUCE ELECTRICAL LOAD TO LESS THAN 20 AMPS, VERIFY THE "STBY ALT ON" ANNUNCIATOR REMAINS ILLUMINATED AND IS NOT BLINKING.
- R. SWITCH THE PRIMARY ALTENATOR FILED SWITCH TO "ON". VERIFY THE "STB ALT ON" ANNUNCIATOR EXTINGUISHES.
- S. REDUCE ENGINE TO IDLE, THEN SHUT ENIGNE DOWN, REINSTALL ALL OPENED PANELS AND MAKE LOG BOOK ENTRY INDICATING ACCOMPLISHMENT OF THIS MODIFICATION.
- CONTINUED AIRWORTHINESS, MAINTENANCE OF THE BC410 ALTERNATOR SYSTEM IS "ON CONDITION". REFER TO B & C SPECIALTY PRODUCTS INC, DOC. ICA—BC410, REV A OR LATER FOR INPSECTION REQUIRMENTS.
- 19. PREMIER AIRCRAFT SALES, INC. AIRPLANE FLIGHT MANUAL SUPPLEMENT DOC. # FMS-N318DS, AS APPROVED, IS REQUIRED TO BE ON-BOARD AIRCRAFT DURING OPERATION

THIS DRAWING CONTAINS
SPECIFICATIONS AND/OR DATA,
TECHNICAL MATERIAL, PROPRIETARY
DESIGNS AND INFORMATION THAT
ARE THE SOLE PROPERTY OF DC
AEROSPACE, LLC.. TO BE HELD
AND TREATED BY ITS RECIPIENT ON
A CONFIDENTIAL BASIS. NO
DISCLOSURE, USE, OR DUPLICATION
SHALL BE MADE WITHOUT PRIOR
WRITTEN PERMISSION OF DC
AEROSPACE, LLC. OR THEIR LEGAL

REPRESENTATIVES.



Eagle Springs 104 Grove Court Centerville, GA. 31028


TITLE: Drawing

BC410 28v ALT, INST'L

Drawn By:	D. Chadwick	Date 3-11-12	DWG NO.:	REV
Approved By:	D. Chadwick	3-11-12	N318DS-24-00	I.R.
			QUEET	-

EFF: DIAMOND DA-40 S.N. 40.1137

1



VIEW OOKING FORWARD - ENGINE

CAREFULLY CLEAN THE GASKET SURFACES, ORIENT THE ALTERNATOR AS SHOWN AND INSTALL IT ON THE ACCESSORY PAD USING A NEW GASKET (ITEM 2), 4 NUTS, (ITEM 3), 4 LOCKWASHERS (ITEM 4) AND 4 FLAT WASHERS (ITEM 5). TORQUE NUTS TO 90 TO 110 IN-ILBS.

***************************************	REMOVED WIRE(S)
	ADDED WIRE(S)
	EXISTING WIRE(S)
	RELOCATED WIRE(S)


TEM	QTY.	PART NUMBR	DESCRIPTION	VENDOR / MFG
1	1	BC410-100-1	14V/28V, 20AMP ALTERNATOR	B & C SPECIALTY PRODUCTS
2	1	MS9134-01	GASKET	QPL
3	4	S804-420	NUT, HEX-HD, 1/4-20UNC	QPL
4	4	MS35333-40	LOCK WASHER, INTERNAL TOOTH, 1/4	QPL
5	4	AN960-416L	FLAT WASHER 1/4	QPL

TITLE: Drawing	BC410 28v ALT. INST'L		REV
DWG NO.:	N318DS-24-00	SHEET 2	

Aug dans




Eagle Springs 104 Grove Court Centerville, GA, 31028



- 1. INSTALL ANNUNCIATOR (ITEM 1) IN PANEL ON PILOTS SIDE AS SHOWN.
- 2. INSTALL STANDBY ALTERNATOR CONTROL SWITCH (ITEM 2) AS SHOWN, ADJACENT TO ANNUNCIATOR (ITEM 1).
- 3. INSTALL CIRCUIT BREAKERS (ITEMS 3, 4, 5) AS SHOWN.
- 4. INSTALL PLACARDS (ITEMS 7, 8, 9) AS SHOWN. TRIM TO FIT.

***************************************	REMOVED WIRE(S)
	ADDED WIRE(S)
	EXISTING WIRE(S)
	RELOCATED WIRE(S







TEM	QTY.	PART NUMBR	DESCRIPTION	VENDOR / MFG
1	1	425-205-1	ANNUNCIATOR	B & C SPECIALTY
2	1	425-401	SWITCH	B & C SPECIALTY
3	1	S878-40	40A CIRCUIT BREAKER	B & C SPECIALTY
4	1	S871-5	5A CIRCUIT BREAKER	B & C SPECIALTY
5	1	S871-1	1A CIRCUIT BREAKER	B & C SPECIALTY
6	1	410-404	ANNUNCIATOR PLACARD	B & C SPECIALTY
7	1	410-402	PLACARD "STBY ALT"	B & C SPECIALTY
8	1	410-401	PLACARD "SENSE"	B & C SPECIALTY
9	1	410-401	PLACARD "FIELD"	B & C SPECIALTY
10	2	MS35214-14	SCREW, PAN HD. 6-32 x.38	QPL

TITLE: Drawing	BC410 28v AL	T. INST'L	REV I.R.
DWG NO.:	N318DS-24-00	SHEET 3	





- RIGHT CIRCUIT BREAKER PANEL (VIEW FROM REAR)
- 1. INSTALL REGULATOR (ITEM 1) AS SHOWN.
- 2. INSTALL 10 AWG JUMPER WIRE FROM MAIN BUS TO 40A ALT CIRCUIT BREAKER "B" SIDE AS SHOWN. INSTALL 10 AWG JUMPERS FROM "B" SIDE OF 40A "ALT CIRCUIT BREAKER TO 1A "SENSE" CIRCUIT BREAKER, INSTALL 10 AWG JUMPER WIRE FROM 1A "SENSE" CIRCUIT BREAKER TO 5A "FIELD" CIRCUIT BREAKER.
- 3. MOUNT THE REGULATOR (ITEM 1) AS SHOWN.
- MATCH DRILL 2 ATTACHMENT HOLES FOR (ITEM 2). USE REGULATOR AS TEMPLATE.
- 5. USE (ITEMS 2, 3) TO SECURE REGULATOR.
- CONNECT AN AIRFRAME GROUND TO THE STUD UNDER THE REGULATOR TERMINAL STRIP. THIS GROUND MUST BE SEPARATE FROM MOUNTING SCREWS OR GROUND TERMINAL PIN 7.



TEM	QTY.	PART NUMBR	DESCRIPTION	VENDOR / MFG
1	1	BC203-20	REGULATOR 28V	B & C SPECIALTY
2	2	10-32	SCREW 10-31 SS	QPL
3	2	10-32	CLIP NUTS 10-32	QPL
4	AR	MIL-W-22759-16/10	WIRE, SINGLE	QPL

023

REMOVED WIRE(S)

ADDED WIRE(S)

EXISTING WIRE(S)

RELOCATED WIRE(S)




FIREWALL, INBD VIEW - FWD-

3



VIEW LOOKING AFT, RH FIREWALL FEEDTHRU

- 1. INSTALL 10 AWG OUTPUT / CURRENT SENSOR (ITEM 1)
 AND FILED HARNESSES (ITEM 2), FROM THE BC410 AFT TO
 THE REGULATOR AND CIRCUIT BREAKER PANEL. USE ADEL
 CLAMPS, (ITEM 3) TO ATTACH THE HARNESSES TO THE
 BACK SIDE OF THE AFT ENGINE COMPARTMENT FWD
 FIREWALL. ROUTE HARNESS THU EXISTING CUTOUT RH
 SIDE FIREWALL AS SHOWN IN FLAG NOTE 3.
- 2. ROUTE THE FIELD HARNESS AND THE THREE COLORED WIRES CODED CURRENT SENSOR WIRES TO THE REGULATOR (BC203-20).
- 3. ROUTE HERE AS SHOWN



INSTRUMENT PANEL

B & C Specialty Products Inc

123 East 4th St, P.O. Box "B", Newton KS 67114-0894 Telephone (316) 283-8000 ***** Fax (316) 283-7400


Manufacturer of Lightweight Electrical Systems

Instructions for Continued Airworthiness for B&C Specialty Products Model BC410 & BC425 Alternators

The B&C Model BC410 or BC425 alternator requires no recurrent maintenance during its service life of 1700 hours. It is recommended that at 1700 hours or less time in service or during engine overhaul the alternator be returned to B&C Specialty Products for factory overhaul.

At each Annual or 100 hour inspection required by the FAA, make the following inspections:

- 1. Note during a normal run-up whether the alternator vibrates or is mechanically noisy. If so, suspect a bearing failure. Bearing failure may also be indicated by gray dust residue around the rear housing cooling slots. If bearing failure is suspected, return the alternator to the factory for repair or replacement.
- 2. Check the alternator externally for security of mounting. If oil is leaking around the alternator base, check the torque of the mounting bolts to be 70 In-Lbs. If there is still a leak, try replacing the gasket. Do not increase torque above 70 In-Lbs.
- 3. Clean the area around the mounting flanges and the casting webs between the mounting flanges and the alternator housing. Check for cracks in the webs as shown in the figure below.



Check for cracks. 4 places

Normal tooling parting lines should not be mistaken for cracks. Any alternator identified as having cracks in any of the four webs must be returned to the factory for repair or replacement.

4. Check for security of alternator wiring. Look for dark discoloration of the copper plated output stud and nut. If it is discolored or corroded, be suspicious of a poor terminal crimp on the output wire.

Disconnect the terminal and clean the output post and nut with a brass wire brush. Replace the crimp terminal by removing enough conductor length to obtain a clean, bright stripped conductor before crimping on a new ring terminal. Re-install the terminal on the output post using a lock washer and nut and torque the nut to 50 In-Lbs.

5. Perform the before takeoff test described under the "Normal Procedures" section of the Airplane Flight Manual Supplement. Alternately, the "Final Test" described in the installation drawing may be used for this test.

Failure due to broken wires or damaged connectors may be corrected in the field using repair procedures complying with the latest revision of AC43.13-xx. All other repairs are by replacement only.

IF THESE UNITS ARE NOT BEING INSTALLED UNDER AN STC, THEY MUST BE ACCOMPANIED BY A ONE TIME FIELD APPROVAL FOR USE ON A TYPE CERTIFICATED AIRCRAFT