
Date	TACH/HOBBS	PSOH	AFTT
6/18/2019	766.6		766.6

Prop Entry

Inspected in accordance with annual inspection per FAR 43 appendix D. Found to be in an airworthy condition and approved for return to service. Refer to WO#G04162 on file at Dillon's Aviation, Inc.



Ernest D. Rawls For Dillon's Aviation, Inc.
AP238764345IA

Date	TACH/HOBBS	ESMOH	ETT
6/18/2019	766.6		766.6

Eng Entry

Performed annual inspection on this engine in accordance with FAR 43 appendix D. Cleaned and gapped all spark plugs cleaned all air and fuel filters. Changed oil and filter. Serviced with 7 quarts Aeroshell 15W/50 and AA48110-2 filter. Checked magneto points and timing. Performed compression check as follows: 1-78/80, 2-76/80, 3-76/80, 4-70/80. Checked and serviced all fluid levels, lubricated controls and washed aircraft. Checked applicable AD's for compliance to date. Performed all work in reference to Lycoming service manual and standard practice as listed in FAR part 43 to return this engine to service in airworthy condition. Refer to WO#G04162 on file at Dillon's Aviation, Inc.

C/W AD 2015-19-07 Fuel injection system inspection per par (e)(1)(ii) and Lycoming MSB342G, next due AFTT: 876.6.


Ernest D. Rawls For Dillon's Aviation, Inc.
AP238764345IA

N Number	Date	TACH/HOBBS	AFTT
N692CJ	6/18/2019	766.6	766.6

AF Entry

Performed annual inspection on this aircraft in accordance with FAR 43 appendix D. Checked all controls for proper rigging and lubricated. Checked all cables for proper tension, checked all structural points, inspected all hoses, lines and wiring. Repacked all wheel bearings, checked tires, wheels and brakes for condition. Inspected ELT in accordance with FAR 91.207(d), next due 06/2020. Checked and serviced all fluid levels, lubricated controls and washed aircraft. Checked applicable AD's for compliance to date. All work performed in reference to Diamond service manual and standard practice as listed in FAR part 43 to return this aircraft to service in airworthy condition. Refer to WO#G04162 on file at Dillon's Aviation, Inc.

*ELT battery due replacement 05/2024.

*ELT remote switch battery due replacement 03/2024.

*Emergency backup battery due 05/2020.


*Air bag EMU due 11/2021.

*Air bag inflator bottles LH dated 11/11 due 11/23 and RH dated 01/12 due 01/24 AmSafe SB 507592-401-25-01.

*Garmin G1000 ICA due 05/2020.

*C/W Power Flow Exhaust ICA, no defects noted, next due 06/2020 or AFTT: 1166.6 whichever occurs first.

*AD 93-05-06 ACS ignition switch due AFTT: 2000.0.


Ernest D. Rawls For Dillon's Aviation, Inc.
AP238764345IA