

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL HC-C2YR-1BF/F8477-4

PROPELLER S/N NS1337B

LOGBOOK # 1

PROPELLER MAINTENANCE RECORD

Position _____

PITCH RANGE

Propeller Model HC-C2YR-1BF

High/Feather _____

Propeller S/N NS1337B

Start Lock _____

Blade Design F8477-4

Low _____

Blade S/N's

Reverse _____

No. 1 L34794

No. 2 L34793

Aircraft Manufacturer Aviat Aircraft Inc.

No. 3 _____

Aircraft Model A-1C-200

No. 4 _____

S/N 3183

No. 5 _____

Registration N65WV

No. 6 _____

Spinner Assembly Part No. C3568-P

Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		
04/23/13	0.0	N/A	0.0	<p>Installed New propeller on New Aviat Aircraft Inc. model <u>A-1C-200</u> serial number <u>3183</u> in accordance with applicable technical information and Aviat Aircraft Inc. Production Certificate No. 704NM.</p> <p><i>Albert Humbert</i> Albert Humbert for Aviat Aircraft Inc.</p>
07/13/14	61.8	N/A	61.8	Annual Inspection. Greased w/ Aeroshell G. <i>J. S. [Signature]</i>
04/22/15	91.6	N/A	91.6	Annual Inspection. Greased w/ Aeroshell G. <i>J. S. [Signature]</i>
07/04/16	106.7	N/A	106.7	Annual Inspection. Greased w/ Aeroshell G. <i>J. S. [Signature]</i>
10/18/17	116.4	N/A	116.4	Annual Inspection. Greased w/ Aeroshell G. <i>J. S. [Signature]</i>



AVIAT
AIRCRAFT, INC

Pitts

672 S. Washington St. Afton, WY 83110

Reg. Number N65WY S/N 3183 Tach Time 130.93 Date 18 January 2019
Model Husky A-1C-200 Propeller Hartzell HC-C2YR-1BF/F8477-4 S/N NS1337B
Prop TT 165.76

Completed 100 hour / Annual inspection. Lubricated with Aeroshell 6 in accordance with Hartzell Propeller Owners Manual 115N rev, 18 Dated February 2018.

I certify that this propeller has been inspected in accordance with a 100 hour/ Annual Inspection and determined to be in an AIRWORTHY condition.

Calvin Cannon AP2863589IA

Calvin Cannon