



The Standard

PROPELLER LOG

ASA-SP-L

Propeller Record General Information

Propeller Manufacturer SENSE NICH

Model 74DM6-0-56

Hub Series # A40435

Date of Manufacture _____

Type _____

Blade # _____

Make/Model

Serial #

Aircraft Installed On:

N8214C

JORDAN PROPELLER SERVICE, INC.
103 East Rhapsody San Antonio, Texas 78216
Certificated Repair Station No. EK2R797K

PROPELLER S/N A40435 HAS BEEN OVERHAULED

Reference Sensenich Propeller Manual SPRM 590.

C/W Service Bulletins R-12A & R-15A.

PERTINENT DETAILS ON FILE UNDER WORK ORDER NUMBER 18324

SIGNED *Barry C. Jordan* DATE 02-23-17

MECHANIC MAKING INSTALLATION ON A/C MUST C/W FAR 43.9

Mech. Cert. # or Repair Station # _____

Year: _____
Date: _____

**Total Time
in Service**

Description

Next Inspection
Due:

**Time Since
Overhaul**

Mech. Cert. # or Repair Station # _____

Date: 2/25/17

Registration: N8214C

Tach: 1737.94

Model: Sensenich M74DM-0-56 S/N: A40435

Propellor TT: 1737.94

Yea

Dat

Nex
Due

Removed and reinstalled propeller following overhaul by Jordan propeller Service. Torqued propeller and safetied, checked track. Performed engine ground run checkout and static RPM check.

Ludvik J. Svetlik
Ludvik J. Svetlik

A&P / IA 3435603

Date:

Next Inspection
Due:

Time Since
Overhaul

Mech. Cert. # or Repair Station #

Year:

Date:

Next Inspection
Due:

Total Time
in Service

Time Since
Overhaul

Description

Mech. Cert. # or Repair Station #

Date: 4/9/19

Registration: N8214C

Tach: 1761.1

Model: Sensenich M74DM-0-56

S/N: A40435

Propellor TSOH: 23.2

Year:

Date:

Next Insj

Due:

Visual checked propeller hub for cracks. Checked propeller mounting and safety. Smoothed minor nicks from propeller blades and inspected for cracks. Inspected spinner and spinner bulkhead. Inspection completed per Far 43 App. D.

Year:

Date:

Next Insj

Due:

I certify that this propellor has been inspected in accordance with an Annual Inspection and is determined to be in airworthy condition.

Ludvik J. Svetlik

A&P / IA 3435603

Year:

Date:

Next Inspection
Due:

Time Since
Overhaul

Mech. Cert. # or Repair Station #